


Hubbell Building Automation  
 Low Voltage Sensors (devices)  
**Requires 33mA each**

**NOTE:**

1. DO NOT attempt to power more than 4 devices, be it sensors or slave packs, from a single power pack.

<p><b>LODT 1-circuit with 1 to 4 sensors</b></p>  <p><b>Building Automation, Inc.</b></p>
--